

# Final Reclamation Inspection

May 5, 2020

Operator: NOBLE ENERGY INC - #100322

Location ID: 319536

Inspection Document #: 697501461

Weld County, CO

SESW Section 11 T4N R65W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: HUWA #11-1  
Location ID: 319536



**Photo 1.** Photo taken from the well location, facing East. Photo illustrates unmanaged List B Colorado noxious weeds, Scotch and Musk thistle.



Inspection Photos  
Location Name: HUWA #11-1  
Location ID: 319536



**Photo 2.** Photo taken from the well location, facing South. See comments under Photo 1.



Inspection Photos  
Location Name: HUWA #11-1  
Location ID: 319536



**Photo 3.** Photo taken from the well location, facing West. See comments under Photo 1.



Inspection Photos  
Location Name: HUWA #11-1  
Location ID: 319536



**Photo 4.** Photo taken from the well location, facing North. See comments under Photo 1.



Inspection Photos  
Location Name: HUWA #11-1  
Location ID: 319536



**Photo 5.** Photo taken from the eastern well location access road, facing West.  
Photo illustrates bare ground with no establishment of desirable plant species.



Inspection Photos  
Location Name: HUWA #11-1  
Location ID: 319536



**Photo 6.** Photo taken from a portion of the well location access road, facing West.  
See comments under Photo 1.



Inspection Photos  
Location Name: HUWA #11-1  
Location ID: 319536



**Photo 7.** Reference photo taken south of the well location access road, facing Southwest. Photo illustrates vegetative growth consisting mostly of smooth brome.



Inspection Photos  
Location Name: HUWA #11-1  
Location ID: 319536



**Photo 8.** Photo taken from the associated offsite tank battery, facing South. Photo illustrates Operator has failed to perform final reclamation activities.