

Inspection Photos May 1, 2020

Location Name: Dwinell Tank Battery Location ID: 324591; Spill ID: 473059; REM 15326; Pit ID: 115239



Location Sign.



Light plant with oily container and rags.

Inspection Photos May 1, 2020

Location Name: Dwinell Tank Battery Location ID: 324591; Spill ID: 473059; REM 15326; Pit ID: 115239



Hose haphazardly on the ground, wheelbarrow full of oily soaked insulation.



Unused equipment.

Inspection Photos May 1, 2020

Location Name: Dwinell Tank Battery Location ID: 324591; Spill ID: 473059; REM 15326; Pit ID: 115239



Hose from previous photo.



Localized oil staining throughout the Location.

Inspection Photos May 1, 2020

Location Name: Dwinell Tank Battery Location ID: 324591; Spill ID: 473059; REM 15326; Pit ID: 115239



Localized oil staining throughout the Location.



Localized oil staining throughout the Location.



Inspection Photos May 1, 2020

Location Name: Dwinell Tank Battery Location ID: 324591; Spill ID: 473059; REM 15326; Pit ID: 115239



Oil impacts from Spill ID 473059 discovered on 03/09/2020.



Oil impacts from Spill ID 473059 discovered on 03/09/2020.



Inspection Photos May 1, 2020

Location Name: Dwinell Tank Battery Location ID: 324591; Spill ID: 473059; REM 15326; Pit ID: 115239



Oil impacts from Spill ID 473059 discovered on 03/09/2020.



Oil impacts from Spill ID 473059 discovered on 03/09/2020 and hose draped over berm.

Inspection Photos May 1, 2020

Location Name: Dwinell Tank Battery Location ID: 324591; Spill ID: 473059; REM 15326; Pit ID: 115239



Tools apparently used in spill response on berm.



Oil impacts from Spill ID 473059 discovered on 03/09/2020.
Note the oil on the outside of the berm.

Inspection Photos May 1, 2020

Location Name: Dwinell Tank Battery Location ID: 324591; Spill ID: 473059; REM 15326; Pit ID: 115239



Oily trash.



Oil impacts from Spill ID 473059 discovered on 03/09/2020. An approximate 5 cubic yard of impacted material is stock piled in NE corner of the swale area to west of tank battery.

Inspection Photos May 1, 2020

Location Name: Dwinell Tank Battery Location ID: 324591; Spill ID: 473059; REM 15326; Pit ID: 115239



Oil impacts from Spill ID 473059 discovered on 03/09/2020. An approximate 15-20 cubic yard of impacted material is stock piled in SW corner of the swale area to west of tank battery.



Oil impacts from Spill ID 473059 discovered on 03/09/2020. An approximate 15-20 cubic yard of impacted material is stock piled in SW corner of the swale area to west of tank battery.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos May 1, 2020

Location Name: Dwinell Tank Battery Location ID: 324591; Spill ID: 473059; REM 15326; Pit ID: 115239



500 bbl crude tank with hose connected



500 bbl produced water tank with load out valve not blind plugged.

Inspection Photos May 1, 2020

Location Name: Dwinell Tank Battery Location ID: 324591; Spill ID: 473059; REM 15326; Pit ID: 115239



Oil impacts from Spill ID 473059 discovered on 03/09/2020.



Oil impacts from Spill ID 473059 discovered on 03/09/2020.

Inspection Photos May 1, 2020

Location Name: Dwinell Tank Battery Location ID: 324591; Spill ID: 473059; REM 15326; Pit ID: 115239



Equipment leaking oil.



Trash. Note: trash throughout Location.



Inspection Photos May 1, 2020

Location Name: Dwinell Tank Battery Location ID: 324591; Spill ID: 473059; REM 15326; Pit ID: 115239



Trash. Note: trash throughout Location.



Unused equipment and trash.



Inspection Photos May 1, 2020

Location Name: Dwinell Tank Battery Location ID: 324591; Spill ID: 473059; REM 15326; Pit ID: 115239



Unused, unlined pit.



Unused, unlined pit.