

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/06/2020

Submitted Date:

05/06/2020

Document Number:

689704658

**FIELD INSPECTION FORM**

Loc ID 311597 Inspector Name: LONGWORTH, MIKE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: PO BOX 370  
City: PARACHUTE State: CO Zip: 81635

**Findings:**

- 13 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211502	WELL	PR	04/06/1998	GW	045-07262	EXXON GM 21-12	PR
259747	WELL	PR	04/09/2001	GW	045-07778	GM 321-12	PR
438288	WELL	PR	02/10/2015	OW	045-22462	GM 411-12	PR
438289	WELL	PR	02/10/2015	OW	045-22463	GM 531-12	PR
438290	WELL	PR	02/04/2015	GW	045-22464	GM 43-12	PR
438291	WELL	PR	02/10/2015	OW	045-22465	GM 342-12	PR
438292	WELL	PR	02/04/2015	GW	045-22466	GM 343-12	PR
438293	WELL	PR	02/09/2015	OW	045-22467	GM 332-12	PR
438294	WELL	PR	02/04/2015	GW	045-22468	GM 443-12	PR
438295	WELL	PR	02/04/2015	GW	045-22469	GM 542-12	PR
438296	WELL	PR	02/04/2015	GW	045-22470	GM 32-12	PR

**General Comment:**

Follow Up Field inspection  
I, Inspector Mike Longworth, conducted a follow up field inspection.  
Corrective actions have not been addressed from 02/25/2020 Inspection # 689704264  
Tank capacities are faded on tank labels.  
Tank capacities are too small to read at distance.  
Install sign to comply with Rule 210.d.  
C.A. Date 04/26/2020

**Location**

Overall Good:

**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Unaddressed corrective action from 02/25/2020 Inspection # 689704264 Tank capacities are faded on tank labels. Tank capacities are too small to read at distance.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	04/26/2020

**Emergency Contact Number:**

Comment:	<input type="text"/>	Date:	<input type="text"/>
Corrective Action:	<input type="text"/>		

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	211502	Type:	WELL	API Number:	045-07262	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	259747	Type:	WELL	API Number:	045-07778	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	438288	Type:	WELL	API Number:	045-22462	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	438289	Type:	WELL	API Number:	045-22463	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	438290	Type:	WELL	API Number:	045-22464	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	438291	Type:	WELL	API Number:	045-22465	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	438292	Type:	WELL	API Number:	045-22466	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	438293	Type:	WELL	API Number:	045-22467	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				

Facility ID: <u>438294</u>	Type: <u>WELL</u>	API Number: <u>045-22468</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

**Producing Well**

Comment: <a href="#">Producing well</a>	
Corrective Action:	Date:

Facility ID: <u>438295</u>	Type: <u>WELL</u>	API Number: <u>045-22469</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

**Producing Well**

Comment: <a href="#">Producing well</a>	
Corrective Action:	Date:

Facility ID: <u>438296</u>	Type: <u>WELL</u>	API Number: <u>045-22470</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

**Producing Well**

Comment: <a href="#">Producing well</a>	
Corrective Action:	Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689704659	Inspection 689704658 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5143551">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5143551</a>