

Inspection Photos

Loc#334640

Operator: Caerus

Inspection Number: 692402154

Inspection Date: 4/29/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to Southeast.

April 29, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Couey Loc#334640



Photo#2:
Area where debris pushed into Interim area.

April 29, 2020



Photo#3:
Area where debris pushed into Interim area.



Photo#4:
Anchor ?

April 29, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#5:
Rutting.

Caerus Couey Loc#334640



Photo#6:
Tamarisk trees in Interim areas.
April 29, 2020

Photo#7:
Russian Olive tree in Interim area.



Photo#8:
Tank Containment.
April 29, 2020



Photo#9:
Tank Containment



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Couey Loc#334640