

Inspection Photos

Loc#334608

Operator: Caerus

Inspection Number: 692402155

Inspection Date: 4/29/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to West.

April 29, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Dumas Loc#334608



Photo#2:
Area where debris pushed into Interim area.

April 29, 2020



Photo#3:
Area where debris pushed into Interim area.



Photo#4:
Debris on Pad.

April 29, 2020



Photo#5:
Debris on Pad.

Caerus Dumas Loc#334608