

Inspection Photos
Location Name: Jack Berger A TB
Location ID: 446604



Photo 1 TB sign



Photo 2 TB

Inspection Photos
Location Name: Jack Berger A TB
Location ID: 446604



Photo 3 Stained soil by load line



Photo 4 Stained soil by crude tank valve

Inspection Photos
Location Name: Jack Berger A TB
Location ID: 446604



Photo 5 Stained soil by crude tank valve



Photo 6 flowlines

Inspection Photos
Location Name: Jack Berger A TB
Location ID: 446604



Photo 7 Gas meter run




Photo 8 TO flowline valves

Inspection Photos
Location Name: Jack Berger A TB
Location ID: 446604



Photo 9 Horizontal Heated Separator



Photo 10 Stained soil outside door of Separator house.

Inspection Photos
Location Name: Jack Berger A TB
Location ID: 446604



Photo 11 stained soil by base of Separator



Photo 12 Stained soil seeping out of Separator house.

Inspection Photos
Location Name: Jack Berger A TB
Location ID: 446604



Photo 13 stained soil inside of Separator




Photo 14 dripping plumbing inside of Separator house.