

Inspection Photos
Location Name: Suckula Farms Inc. E 1
Location ID: 317688



Photo 1 WH sign

Photo 2 WH

Inspection Photos
Location Name: Suckula Farms Inc. E 1
Location ID: 317688



Photo 3 PU

Photo 4 Transformers, meter box and electric panel

Inspection Photos
Location Name: Suckula Farms Inc. E 1
Location ID: 317688



Photo 5 TB sign

Photo 6 TB

Inspection Photos
Location Name: Suckula Farms Inc. E 1
Location ID: 317688



Photo 7 stained soil has been removed

Photo 8 weeds have been removed from valve assembly

Inspection Photos
Location Name: Suckula Farms Inc. E 1
Location ID: 317688




Photo 9 flow lines have been TO

Photo 10 flow lines have been TO

Inspection Photos
Location Name: Suckula Farms Inc. E 1
Location ID: 317688



Photo 11 Horizontal Heated Separator has had weeds removed

Photo 12 weeds have been removed from around gas meter run