



## Form Information

Form Name:	<b>Compliance Follow Up Form</b>
Submitter Name:	Kenneth Canterbury (kenneth.canterbury@crossfire-llc.com)
Submission Date:	Apr 28, 2020 12:40:29 PM MDT
Server Receive Date:	Apr 28, 2020 12:42:32 PM MDT
Reference Number:	20200428-18140941302
Location:	N La Boca Canyon Rd, Ignacio, CO 81137, USA Apr 28, 2020 12:36:09 PM MDT [ <a href="#">View Map</a> ]

## Information

Name	kenneth.canterbury@crossfire-llc.com
Date	Apr 6, 2020
Well Name	WIRT GAS UNIT F 1
Location Name (Other)	WIRT GAS UNIT E1
API Number	50670786800
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Erosion Repairs Install Rock Run Down Clean up Operator Debris Spot seeding

Photo of first corrective action completed



Completed work description Corrective Action 1

Photo of second corrective action completed

Compliance inspection



Completed work description of corrective action 2  
 Photo of third corrective action completed

Spot seeded



Completed work description of corrective action 3  
 Photo of fourth corrective action completed

Erosion repair



Completed work description  
 Completed work description of corrective action 4  
 Additional photos

Rip Rap run down  
 Spot seeded and picked up trash



Summary of all work completed

Spot seeded, fixed erosion, installed rock run down  
and cleaned up trash