

Inspection Photos
Location Name: KODAK SOUTH FD PAD 28-222HN
Location ID: 306149



Colorado Oil and Gas Conservation Commission
40.45279, -104.86405, 1424.3m, 13°
May 6, 2020 15:23:43

Photo 1: Wellhead Sign




Colorado Oil and Gas Conservation Commission
40.4528, -104.86406, 1425.4m, 35°
May 6, 2020 15:23:49

Photo 2: Wellhead



Inspection Photos
Location Name: KODAK SOUTH FD PAD 28-222HN
Location ID: 306149



Colorado Oil and Gas Conservation Commission
40.4528, -104.86404, 1424.7m, 21°
May 6, 2020 15:23:53

Photo 3: Unused equipment



Colorado Oil and Gas Conservation Commission
40.45285, -104.86404, 1424.3m, 73°
May 6, 2020 15:24:07

Photo 4: Unused equipment



Inspection Photos

Location Name: KODAK SOUTH FD PAD 28-222HN

Location ID: 306149



Photo 5: Wellhead Sign



Photo 6: Unused equipment



Inspection Photos

Location Name: KODAK SOUTH FD PAD 28-222HN

Location ID: 306149



Colorado Oil and Gas Conservation Commission
40.45283, -104.86404, 1425.0m, 16°
May 6, 2020 15:24:49

Photo 7: Wellhead Sign



Colorado Oil and Gas Conservation Commission
40.45281, -104.86404, 1423.7m, 20°
May 6, 2020 15:24:55

Photo 8: Wellhead



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: KODAK SOUTH FD PAD 28-222HN

Location ID: 306149



Colorado Oil and Gas Conservation Commission
40.45278, -104.86405, 1425.0m, 349°
May 6, 2020 15:25:01

Photo 9: stained soil



Colorado Oil and Gas Conservation Commission
40.45277, -104.86403, 1429.3m, 22°
May 6, 2020 15:25:32

Photo 10: Wellhead Sign

Inspection Photos
Location Name: KODAK SOUTH FD PAD 28-222HN
Location ID: 306149



Photo 11: Wellhead



Photo 12: Stained soil/unused equipment



Inspection Photos
Location Name: KODAK SOUTH FD PAD 28-222HN
Location ID: 306149



Photo 13: Wellhead Sign



Photo 14: Wellhead



Inspection Photos
Location Name: KODAK SOUTH FD PAD 28-222HN
Location ID: 306149




Photo 15: Stained soil not removed



Photo 16: Wellhead; NO SIGN DISPLAYED

Inspection Photos

Location Name: KODAK SOUTH FD PAD 28-222HN

Location ID: 306149



Photo 17: Stained soil not removed



Photo 18: Tank removed