

# *Inspection Photos*

*Loc#323904*

*Operator: Caerus*

*Inspection Number: 692402156*

*Inspection Date: 4/29/20*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location to Northeast. Insert - Penstemon

April 29, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Caerus Roe Loc#323904





Photo#2:  
Anchors.

April 29, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#3:  
Anchors.

Caerus Roe Loc#323904