

Inspection Photos

Loc#323879

Operator: Caerus

Inspection Number: 692402157

Inspection Date: 4/29/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources




Photo#1:
Overview of Location to West.

April 29, 2020



Photo#2:
Area No longer needed for use.

April 29, 2020



Photo#3:
Aerial; showing areas no longer in use.

April 29, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Schaffer Loc#323879



Photo#4:
Anchor, not marked

April 29, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources




Photo#5:
Point where sediment is migrating off Pad.

Caerus Schaffer Loc#323879



Photo#6:
Access road Culvert.

April 29, 2020



Photo#7:
Erosion down gradient of access road culvert.