

Inspection Photos
Operator: BP America
API#: 067-08334
Date: 5/5/2020



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the southern project area from the southwestern corner facing eastward. Revegetation is progressing with grasses such as crested wheatgrass and western wheatgrass.



Photo 3. View of reference area open grass field, comprised of smooth brome.