

# *Inspection Photos*

*Loc#334933*

*Operator: Caerus*

*Inspection Number: 692402158*

*Inspection Date: 4/29/20*





Photo#1:  
Overview of Location.

April 29, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Caerus HMR Loc#334933



Photo#2:  
Interim reclamation.

April 29, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Caerus HMR Loc#334933



Photo#4:  
Anchor with T post, no bright color.

April 29, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Caerus HMR Loc#334933