

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402391935

Date Received:  
05/06/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1675 BROADWAY, STE 2800  
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Victoria Dizghinjili</u>	<u>303-825-4822</u>	<u>vdizghinjili@kpk.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 699501085  
Inspection Date: 04/20/2020 FIR Submit Date: 04/20/2020 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: KP KAUFFMAN COMPANY INC Company Number: 46290  
Address: 1675 BROADWAY, STE 2800  
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 159787

Location Name: Facility Number: 5 County: WELD  
Qtrqr: NESE Sec: 4 Twp: 1N Range: 67W Meridian: 6  
Latitude: 40.078220 Longitude: -104.888730

FACILITY - API Number: 05-123-00 Facility ID: 239677

Facility Name: VERA L MCCANNON Number: 1  
Qtrqr: NESE Sec: 4 Twp: 1N Range: 67W Meridian: 6  
Latitude: 40.078220 Longitude: -104.888730

CORRECTIVE ACTIONS:

1 CA# 138203

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Date: 09/18/2019

Response: CA COMPLETED Date of Completion: 04/28/2020

Operator Comment: Stained soil around tanks, pump house, and in separator house has been removed. Please see attached pictures.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**2** CA# 138204

Corrective Action: Install adequate BMB for storage of materials that could result in the discharges causing pollution of surface waters per rule 1002 f (2)B

Date: 09/18/2019

Response: CA COMPLETED

Date of Completion: 04/28/2020

Operator Comment: Storage for chemicals has been installed. Please see attached picture.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**3** CA# 138205

Corrective Action: Properly treat or dispose of oily waste in accordance with 907.e

Date: 09/18/2019

Response: CA COMPLETED

Date of Completion: 04/28/2020

Operator Comment: Stained soil around tanks, pump house, and in separator house has been removed. Please see attached pictures.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**4** CA# 138206

Corrective Action: Measure gas per Rule 329.

Date: 09/18/2019

Response: CA COMPLETED

Date of Completion: 04/28/2020

Operator Comment: Gas meter has been updated.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Victoria Dizghinjili

Signed: \_\_\_\_\_

Title: Engineering Tech

Date: 5/6/2020 6:07:58 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402391956	CA PIC1
402391957	CA PIC2
402391958	CA PIC3

Total Attach: 3 Files