

## Inspection Photos

Location Name: GORDON ENGINEERING INC FEDERAL-69S97W /32NWSE

Location ID: 312560



Photo #1120 from entrance to location



Photo #0720 from inspection #699800705 conducted on 3/6/20.

## Inspection Photos

Location Name: GORDON ENGINEERING INC FEDERAL-69S97W /32NWSE

Location ID: 312560



**Photo #1124 Debris and weeds around equipment.**



**Photo #0721 from inspection #699800705 conducted on 3/6/20.**

## Inspection Photos

Location Name: GORDON ENGINEERING INC FEDERAL-69S97W /32NWSE

Location ID: 312560



Photo #1125 Debris and weeds around equipment.



Photo #0719 from inspection #699800705 conducted on 3/6/20.

## Inspection Photos

Location Name: GORDON ENGINEERING INC FEDERAL-69S97W /32NWSE

Location ID: 312560



**Photo #1126 Unused piping by meter run.**