

Inspection Photos

Location Name: LARAMIE ENERGY LLC Horseshoe Canyon /2-31 Pad

Location ID: 312568



Photo #1128 from entrance to location



Photo #1129 Multiple places with unused equipment on location.

Inspection Photos

Location Name: LARAMIE ENERGY LLC Horseshoe Canyon /2-31 Pad

Location ID: 312568



Photo #1130 Multiple places with unused equipment on location.



Photo #1131 Stained soil inside tank containment.