

Inspection Photos

Location Name: GORDON ENGINEERING INC FEDERAL-69S97W /32SWNW

Location ID: 334074



Photo #1132 from entrance to location



Photo #1133 Weeds growing on location.

Inspection Photos

Location Name: GORDON ENGINEERING INC FEDERAL-69S97W /32SWNW

Location ID: 334074



Photo #1134 Multiple holes in tank containment liner.