

Inspection Photos

API: 055-06243

Operator: PETROGLYPH OPERATING CO

Inspection Date: 5/4/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 055-06243 | Date: 5/4/2020

Inspection Photos



Photo 1. Facing northwest along the reclaimed access road. Perennial vegetation is well established along the former road and establishment is much improved since last years inspection. The pile of mulch and twine previously observed has been removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06243 | Date: 5/4/2020

Inspection Photos



Photo 2. Facing northwest along the reclaimed access road. Perennial vegetation is well established along the former road and consists of Western wheat grass, Sand dropseed, Blue grama among other species.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 055-06243 | Date: 5/4/2020

Inspection Photos



Photo 3. Facing southwest toward the location. Perennial vegetation is well established throughout the location and consists of Western wheat grass, Sand dropseed, Blue grama among other species.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06243 | Date: 5/4/2020

Inspection Photos



Photo 4. Facing north at the location. Perennial vegetation is well established throughout the location and consists of Western wheat grass, Sand dropseed, Blue grama among other species.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06243 | Date: 5/4/2020

Inspection Photos



Photo 5. Facing east at the location. Perennial vegetation is well established throughout the location and consists of Western wheat grass, Sand dropseed, Blue grama among other species.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06243 | Date: 5/4/2020

Inspection Photos



Photo 6. Facing southeast at the location. Perennial vegetation is well established throughout the location and consists of Western wheat grass, Sand dropseed, Blue grama among other species.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06243 | Date: 5/4/2020

Inspection Photos



Photo 7. View of groundcover at the location. Perennial vegetation is well established throughout the location and consists of Western wheat grass, Sand dropseed, Blue grama among other species.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06243 | Date: 5/4/2020

Inspection Photos



Photo 8. Facing northwest toward the surrounding undisturbed reference area. Vegetation consists of Pinion Juniper woodland and Blue grama grassland.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06243 | Date: 5/4/2020