

# *Inspection Photos*

*Loc#334576*

*Operator: Caerus*

*Inspection Number: 692402159*

*Inspection Date: 4/29/20*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location.

April 29, 2020





Photo#2:  
Interim reclamation.

April 29, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Caerus Couey Loc#334576





Photo#3:  
Open gauge housing.



Photo#4:  
Close up of open gauge housing.

April 29, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Caerus Couey Loc#334576





Photo#5:  
BMPs needing maintenance.



Photo#6:  
BMPs needing maintenance.

April 29, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Caerus Couey Loc#334576





Photo#7:  
Debris on site



Photo#8:  
Debris on site.

April 29, 2020