

Inspection Photos

Loc#334679

Operator: Caerus

Inspection Number: 692402160

Inspection Date: 4/29/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location.

April 29, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Couey Loc#334679



Photo#2:
Weedy portion of Interim reclamation.

April 29, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Couey Loc#334679



Photo#3:
BMPs needing maintenance.



Photo#4:
BMPs needing maintenance.

April 29, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Couey Loc#334679