

**Inspection Photos**  
**Location Name: Pratt #2**  
**Location ID: 318975**



**Photo 1 WH's and KPK swabbing Pratt #13-29D**

**Photo 2 TNK BTRY Tank NFPA placards are either faded or missing.**

Inspection Photos  
Location Name: Pratt #2  
Location ID: 318975



Photo 3 stained soil around crude oil load out line


Photo 4 Produced water tank has no volume sign or markings on tank.

# Inspection Photos

Location Name: Pratt #2  
Location ID: 318975



Colorado Oil and Gas Conservation Commission  
40.01821, -105.03241, 1552.8m  
May 7, 2020 11:05:59



Colorado Oil and Gas Conservation Commission  
40.01821, -105.03224, 1551.7m  
May 7, 2020 11:08:24

Photo 5 Lines not marked or LOTO

Photo 6 Meter test cards over annual test

**Inspection Photos**  
**Location Name: Pratt #2**  
**Location ID: 318975**



**Photo 7 stained soil in separator containment**



**Photo 8 Meter house/seps and ECD's**