

Inspection Photos
Operator: BP America
API#: 067-07792
Date: 5/5/2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern fill slope from the southeastern corner facing northward. Revegetation is progressing largely with western wheatgrass, rubber rabbitbrush, and sand dropseed.



Photo 3. View of the northern project area from the northwestern corner facing eastward.



Photo 4. View of reference area comprised of pinyon-juniper woodland with sagebrush, squaw apple, blue gramma, and western wheatgrass.