

Inspection Photos
Operator: BP America
API#: 067-07002
Date: 5/5/2020



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the southern fill slope from the southeastern corner facing westward. Revegetation is progressing with western wheatgrass and smooth brome.



Photo 3. View of the northeastern project area. Area appears to be seeded and mulched.



Photo 4. View of the western fill slope facing southward. It appears that spot seeding/mulch conducted in portions of this slope.



Photo 5. View of reference area comprised of pinyon-juniper woodland with sagebrush, smooth brome, and western wheatgrass.