

Inspection Photos
Operator: BP America
API#: 067-08499
Date: 5/5/2020



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the southern fill slope from the southeastern corner facing westward. Revegetation is progressing with western wheatgrass, intermediate wheatgrass, and smooth brome.



Photo 3. View of reference area comprised of mixed grasses such as smooth brome and western wheatgrass in a landscape mosaic with pinyon and juniper woodland.