

Inspection Photos

Loc#334865

Operator: Caerus

Inspection Number: 692402163

Inspection Date: 4/29/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location.

April 29, 2020




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Couey Loc#334865



Photo#2:



Photo#3:

April 29, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Couey Loc#334865



Photo#4:
Interim area.

April 29, 2020



Photo#5:
Cheat grass in Interim.

Caerus Couey Loc#334865