

Inspection Photos

Loc#334789

Operator: Caerus

Inspection Number: 692402164

Inspection Date: 4/29/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location.

April 29, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Schaffer Loc#334789



Photo#2:
Anchor, marked with T Post.



Photo#3:
Stormwater area of concern.

April 29, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Schaffer Loc#334789



Photo#4:
Interim area.

April 29, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#5:
Interim area.

Caerus Schaffer Loc#334789