

Inspection Photos
Location Name: Genesis 9-2, 3
Location ID: 319579



Photo 1: Pumpjack Sign



Photo 2: Pumpjack; equipment connected

Inspection Photos
Location Name: Genesis 9-2, 3
Location ID: 319579



Photo 3: Stained soil



Photo 4: Pumpjack Sign



Inspection Photos
Location Name: Genesis 9-2, 3
Location ID: 319579



Photo 5: Pumpjack; equipment connected



Photo 6: Tank Removed

Inspection Photos
Location Name: Genesis 9-2, 3
Location ID: 319579



Photo 7: Tank Battery Sign



Photo 8: Tank Battery

Inspection Photos
Location Name: Genesis 9-2, 3
Location ID: 319579



Photo 9: Inadequate berm



Photo 10: Inadequate berm



Inspection Photos
Location Name: Genesis 9-2, 3
Location ID: 319579



Photo 11: Tank not grounded



Photo 12: Unused equipment



Inspection Photos
Location Name: Genesis 9-2, 3
Location ID: 319579



Photo 13: Riser LO/TO



Photo 14: Risers LO/TO

Inspection Photos
Location Name: Genesis 9-2, 3
Location ID: 319579



Photo 15: Equipment removed