

Inspection Photos
Operator: BP America
API#: 067-09644
Date: 5/5/2020



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern fill slope from the southeastern corner facing northward. Revegetation is progressing with western wheatgrass, crested wheatgrass, and intermediate wheatgrass.



Photo 3. View of the western project area from the southwestern corner facing northward.



Photo 4. View of reference area comprised of mixed grasses such as smooth brome and western wheatgrass.