

Inspection Photos
Location Name: ROTH-66N64W /30NWSW
Location #: 323450




Photo #1
Roth 12-30 (05-123-13046) Wellsite
Shut-In | SI



Photo #2
Roth 12-30 Battery site
Inactive | Shut-down