

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/07/2020

Submitted Date:

05/07/2020

Document Number:

701000693**FIELD INSPECTION FORM**Loc ID 337904 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 5057 KELLER SPRINGS RD STE 650City: ADDISON State: TX Zip: 75001**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Beard, Alyssa		regulatory@foundationenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289564	WELL	PR	12/01/2007	GW	125-10739	STULTS 32-19	PR

General Comment:Routine Inspection

Location

Lease Road:			
Type	Access		
comment:	Trail through farm ground		
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	Metal panels around unit and wellhead		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:	Jensen unit		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Kohler gas engine		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Gas scrubber		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:		
Type		

Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	289564	Type:	WELL	API Number:	125-10739	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Casing production. Central meter run for (Stults 42-19 and 32-19) 1690' NE of wellhead on west side of CR BB								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Other	Pass			

Comment: Location and access are farmed over

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT