

Inspection Photos
Location Name: RAINBOW #1
Spill ID 444861



Photo 1 – Location photo



Photo 2 – Location photo

Inspection Photos
Location Name: RAINBOW #1
Spill ID 444861



Photo 3 – Location photo



Photo 4 – Minor soil staining observed at base of tank

Inspection Photos
Location Name: RAINBOW #1
Spill ID 444861



Photo 5 – Spill ID 444861 (12/30/2015) is still open in the COGCC database at this location. Spill reports document historic impacts discovered area of a former concrete produced water vault.



Photo 6 – 2015 Google Earth Imagery showing location of former produced water vault