

Inspection Photos
Location Name: Lilli Unit 8-12
Location ID: 326921



Photo 1 – Wellhead Sign



Photo 2 – Weeds actively growing



Inspection Photos
Location Name: Lilli Unit 8-12
Location ID: 326921



Photo 3 – Well is SI/TA – Install Tags to Comply with Document #401474555



Photo 4 – Wellhead