

Inspection Photos

API: 071-08352

Operator: TIMBER CREEK OPERATING

Inspection Date: 5/8/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08352 | Date: 5/8/2020

Inspection Photos



Photo 1. Facing toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08352 | Date: 5/8/2020

Inspection Photos



Photo 2. Oil on engine skid and on ground near engine skid appears to have been cleaned up. There is still some spotting stains around engine skid. Operator will need to inspect and maintain.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08352 | Date: 5/8/2020

Inspection Photos



Photo 3. The well sign is posted t the meter shed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08352 | Date: 5/8/2020

Inspection Photos




Photo 4. Facing toward the produced water pit.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08352 | Date: 5/8/2020

Inspection Photos



Photo 5. Facing toward the fill slope which is stabilized with vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08352 | Date: 5/8/2020