

# Inspection Photos

API: 071-09120

Operator: TIMBER CREEK OPERATING

Inspection Date: 5/8/2020



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09120 | Date: 5/8/2020

## Inspection Photos



**Photo 1.** Facing southwest toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09120 | Date: 5/8/2020

## Inspection Photos



**Photo 2.** It appears stained soil has been cleaned up. There is some oil on engine skid. Operator will need to inspect and cleanup if needed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09120 | Date: 5/8/2020

## Inspection Photos



**Photo 3.** Facing toward the produced water pit.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09120 | Date: 5/8/2020

## Inspection Photos



**Photo 4.** Facing toward the fill slope which is stabilized with vegetation.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09120 | Date: 5/8/2020