

# Inspection Photos

API: 071-09108

Operator: TIMBER CREEK OPERATING

Inspection Date: 5/8/2020



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-09108 | Date: 5/8/2020

## Inspection Photos



**Photo 1.** Facing southwest along the access road. The road has been graded and culverts are maintained. Rock sock check dams have been installed along the side. The check dams will need to be monitored to ensure stormwater does not flow around the sides.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09108 | Date: 5/8/2020



## Inspection Photos



**Photo 2.** The culvert along the access road has been maintained and BMP's and area of erosion has been repaired.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09108 | Date: 5/8/2020

## Inspection Photos



**Photo 3.** Facing southwest toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09108 | Date: 5/8/2020



## Inspection Photos



**Photo 4.** Facing toward the wellhead.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09108 | Date: 5/8/2020

## Inspection Photos



**Photo 5.** The oil on the engine skid has been cleaned up since previous inspection.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09108 | Date: 5/8/2020