

Location Name: – Ward and Son Operating - Loc ID 317166

Inspection Date: 05/06/2020



Photo # 1 –

Location Name: – Ward and Son Operating - Loc ID 317166

Inspection Date: 05/06/2020



Photo # 2 – Crude tank battery view SSE



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: – Ward and Son Operating - Loc ID 317166

Inspection Date: 05/06/2020



Photo # 3 – Separator view NNE



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: – Ward and Son Operating - Loc ID 317166

Inspection Date: 05/06/2020



Photo # 4 – Oil skim tank outfall to produced water pit ID 117639



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: – Ward and Son Operating - Loc ID 317166  
Inspection Date: 05/06/2020



Photo # 5 – Produced water pit ID 117639 view NNE



Location Name: – Ward and Son Operating - Loc ID 317166

Inspection Date: 05/06/2020



Photo # 6 – Produced water pit ID 117639 view NNW. Vacuum truck on site removing crude oil from surface of pit. Wind from SSE.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: – Ward and Son Operating - Loc ID 317166

Inspection Date: 05/06/2020



Photo # 7 – Produced water pit ID 117639. Vacuum truck on site removing crude oil from surface of pit. Wind from SSE.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: – Ward and Son Operating - Loc ID 317166

Inspection Date: 05/06/2020



Photo # 8 – Produced water pit ID 117639 view south along east side. Vacuum truck operator working each corner as per prevailing wind.



Location Name: – Ward and Son Operating - Loc ID 317166

Inspection Date: 05/06/2020



Photo # 9 – Produced water pit ID 117639 view southwest at produced water and “brown water” oil skim tank



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources