

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/01/2020

Submitted Date:

05/04/2020

Document Number:

689704630

FIELD INSPECTION FORM
 Loc ID: 335881
 Inspector Name: LONGWORTH, MIKE
 On-Site Inspection: ☐
 2A Doc Num:
Operator Information:

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

16 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Leonard, Mike		mike.leonard@state.co.us	
, Caerus Piceance		COGCC.inspections@caerus oilandgas.com	Piceance inspections only
Arauza, Steven		steven.arauza@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290068	WELL	PR	04/01/2019	GW	045-13978	CHEVRON 33D-7D	SI
290069	WELL	PR	04/01/2019	GW	045-13977	CHEVRON 33B-7D	SI
290070	WELL	SI	10/01/2019	GW	045-13976	CHEVRON 32B-7D	SI
290071	WELL	SI	01/01/2019	GW	045-13975	CHEVRON 22A-7D	SI
290072	WELL	PR	04/01/2019	GW	045-13974	CHEVRON 23B-7D	SI
290073	WELL	PR	08/01/2019	GW	045-13973	CHEVRON 33A-7D	SI
290074	WELL	PR	04/01/2019	GW	045-13972	CHEVRON 32A-7D	SI
290075	WELL	PR	04/01/2019	GW	045-13971	CHEVRON 32D-7D	SI
290076	WELL	PR	08/01/2019	GW	045-13970	CHEVRON 23A-7D	SI
290077	WELL	PR	04/01/2019	GW	045-13969	CHEVRON 21D-7D	SI
290078	WELL	PR	07/01/2019	GW	045-13968	CHEVRON 22D-7D	SI

General Comment:

Request from NW Inspection Supervisor to check on possible rock slide on location.
 On Friday 05/01/2020 at approximately 1115 hours, I, Inspector Mike Longworth, conducted a field inspection.
 Contact made with Flyod Richardson Chevron Rep. Contractor and Chad Thompkins Caerus Production on location.
 Rocks came off from above cut slope area causing damages to gas gathering line, separators, chemical container at wells, and metal berm around tank battery. Wells are shut in and tanks in battery shut in at tank valves. Crew on location with 2 backhoes clearing rocks and removal of damaged chemical contain at wells.

LocationOverall Good: ☒

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
Other	WELLHEAD			
Comment:	Spilled contents of chemical container at wells. Stained ground around well Chevron 32A-7D.			
Corrective Action:	Remove free fluids within 24 hrs and contact COGCC EPS staff per Rule 906.b.			Date: 05/04/2020

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity		Permeability (Wall)		Permeability (Base)		Maintenance	
Comment:								
Corrective Action:							Date:	
Contents	#	Capacity	Type			Tank ID	SE GPS	
CONDENSATE	1	400 BBLS	STEEL AST				,	
Comment:								
Corrective Action:							Date:	

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Insufficient		Inadequate
Comment: Damage to metal berm around tank battery.				
Corrective Action: Repair berm before further movement of fluids or with in 30 days.				Date: 05/31/2020

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 290068 Type: WELL API Number: 045-13978 Status: PR Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: Shut in due to rock slide on location.

Corrective Action: _____ Date: _____

Facility ID: 290069 Type: WELL API Number: 045-13977 Status: PR Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: Shut in due to rock slide on location.

Corrective Action: _____ Date: _____

Facility ID: 290070 Type: WELL API Number: 045-13976 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: Shut in due to rock slide on location.

Corrective Action: _____ Date: _____

Facility ID: 290071 Type: WELL API Number: 045-13975 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: Shut in due to rock slide on location.

Corrective Action: _____ Date: _____

Facility ID: 290072 Type: WELL API Number: 045-13974 Status: PR Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: Shut in due to rock slide on location.

Corrective Action: _____ Date: _____

Facility ID: 290073 Type: WELL API Number: 045-13973 Status: PR Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: Shut in due to rock slide on location.

Corrective Action: _____ Date: _____

Facility ID: 290074 Type: WELL API Number: 045-13972 Status: PR Insp. Status: SI

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Shut in due to rock slide on location.

Corrective Action: _____ Date: _____

Facility ID: 290075 Type: WELL API Number: 045-13971 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Shut in due to rock slide on location.

Corrective Action: _____ Date: _____

Facility ID: 290076 Type: WELL API Number: 045-13970 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Shut in due to rock slide on location.

Corrective Action: _____ Date: _____

Facility ID: 290077 Type: WELL API Number: 045-13969 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Shut in due to rock slide on location.

Corrective Action: _____ Date: _____

Facility ID: 290078 Type: WELL API Number: 045-13968 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Shut in due to rock slide on location.

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
Compaction	Pass					
		Compaction	Pass			
		Gravel	Pass			
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402388154	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5140281
689704631	Inspection 689704630 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5140280