

**Inspection Photos**  
**Location Name: Thompson Price 2**  
**Location ID: 320156**



**Pic 1 stained soil chemical storage with no containment**



**Pic 2**

**Inspection Photos**  
**Location Name: Thompson Price 2**  
**Location ID: 320156**



**Pic 3**



**Pic 4 stained soil**



**Inspection Photos**  
**Location Name: Thompson Price 2**  
**Location ID: 320156**



**Pic 5**



**Pic 6 separator house leaks**