

Inspection Photos
Location Name: McCallum Unit 7
Location ID: 324589



Photo 1. Overview of location taken facing north.

