

Inspection Photos
Operator: BP America
API#: 067-05115
Date: 5/8/2020



Photo 1. View of the southern project area from the well pad entrance facing center. Erosional channels are lined with rock, Russian thistle debris is removed.



Photo 2. View of the northern well pad from the western edge facing center. Russian thistle debris is removed.



Photo 3. View of the central fill slope facing westward. Cobble lined rundowns placed in erosional features.



Photo 4. View of reference area comprised of open sagebrush shrubland with herbaceous understory (ie: western wheatgrass, blue grama)