

Final Reclamation Inspection

May 7, 2020

Operator: NOBLE ENERGY INC - #100322

Location ID: 329582

Inspection Document #: 697501483

Weld County, CO

NWNW Section 32 T5N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: CAMPBELL BB #32-4
Location ID: 329582



Photo 1. Photo taken from the associated offsite tank battery location, facing North. Photo illustrates Operator has failed to perform final reclamation activities and remove all equipment.

Inspection Photos
Location Name: CAMPBELL BB #32-4
Location ID: 329582



Photo 2. Google Earth aerial imagery taken 9/6/2013 during active operations illustrates the associated offsite tank battery area.

Inspection Photos
Location Name: CAMPBELL BB #32-4
Location ID: 329582



Photo 3. Close up photo taken of the equipment remaining at the associated offsite tank battery location, facing North. See comments under Photo 1.

Inspection Photos
Location Name: CAMPBELL BB #32-4
Location ID: 329582



Photo 4. Photo taken north of the well location/well location access road, facing South. Photo illustrates no evidence of oil and gas development. Well location/well location access road appear reflective of reference crop areas.