

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/11/2020

Submitted Date:

05/11/2020

Document Number:

700700667**FIELD INSPECTION FORM**

Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
 335379 _____ Ramsey, Scott _____ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10531Name of Operator: GRIZZLY OPERATING LLCAddress: 5847 SAN FELIPE #3000City: HOUSTON State: TX Zip: 77057**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:17 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, Grizzly		scollett@grizzlyenergyllc.com	
, Grizzly		aaxelson@grizzlyenergyllc.com	
, Grizzly		sgghan@grizzlyenergyllc.com	SR. EH&S

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
263512	WELL	PR	04/05/2005	GW	045-08133	BRYNILDSON 13C-20-692	PR
276580	WELL	PR	03/13/2009	GW	045-10488	BRYNILDSON 13B-20-692	PR
276581	WELL	PR	05/31/2005	GW	045-10487	BRYNILDSON 12A-20-692	PR
276741	WELL	PR	03/01/2009	GW	045-10513	BRYNILDSON 13D-20-692	PR
297757	WELL	PR	03/16/2009	GW	045-16952	BRYNILDSON 12C-20-692	PR
297758	WELL	PR	03/06/2009	GW	045-16953	BRYNILDSON 22A-20-692	PR
297759	WELL	PR	03/01/2009	GW	045-16954	BRYNILDSON 22B-20-692	PR
297760	WELL	PR	03/01/2009	GW	045-16955	BRYNILDSON 22C-20-692	PR
297761	WELL	PR	03/11/2009	GW	045-16956	BRYNILDSON 23B-20-692	PR
297762	WELL	PR	03/05/2009	GW	045-16957	BRYNILDSON 23C-20-692	PR
297763	WELL	PR	02/25/2009	GW	045-16958	BRYNILDSON 23D-20-692	PR
297764	WELL	PR	03/10/2009	GW	045-16959	BRYNILDSON 12B-20-692	PR

General Comment:

COGCC Inspection Report Summary

On Monday 5/11/20 at approximately 8:00 AM, I, Inspector Scott Ramsey, conducted a routine inspection at Grizzly Brynildson 13C, at Location # 335379 in Garfield Colorado.

While there, I observed normal production operations.

This is a summary of inspection report.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911		
Corrective Action:		Date:	

Good Housekeeping:

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:				corrective date
Type: Ancillary equipment	# 2			
Comment:	chemical tanks			
Corrective Action:				Date:
Type: Emission Control Device	# 1			
Comment:				
Corrective Action:				Date:
Type: Plunger Lift	# 12			
Comment:				
Corrective Action:				Date:
Type: Bird Protectors	# 10			
Comment:				
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 12			
Comment:				
Corrective Action:				Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	6	500 BBLs	HEATED STEEL AST		,	
Comment:	Three (3) tanks are not heated					
Corrective Action:						Date:

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:	Date:		

Flaring:

Type			
Comment:			
Corrective Action:	Date:		

Inspected Facilities									
Facility ID:	263512	Type:	WELL	API Number:	045-08133	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	276580	Type:	WELL	API Number:	045-10488	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	276581	Type:	WELL	API Number:	045-10487	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	276741	Type:	WELL	API Number:	045-10513	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	297757	Type:	WELL	API Number:	045-16952	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	297758	Type:	WELL	API Number:	045-16953	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	297759	Type:	WELL	API Number:	045-16954	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	297760	Type:	WELL	API Number:	045-16955	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				

Facility ID:	297761	Type:	WELL	API Number:	045-16956	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Facility ID:	297762	Type:	WELL	API Number:	045-16957	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Facility ID:	297763	Type:	WELL	API Number:	045-16958	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Facility ID:	297764	Type:	WELL	API Number:	045-16959	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON

Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Waddles		Gravel				
Rip Rap		Rip Rap				
Berms		Check Dams				
Ditches		Culverts				
Gravel		Ditches				

Comment:

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT
Attached Documents
 You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700700672	Photos for Brynildson 13C	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5147158