

Inspection Photos
Location Name: ROTH-66N64W /30SWNE
Location #: 329404



Photo #1

Roth A 30-7 (05-123-17294) Wellsite

Plugged & Abandoned | PA

NOT cut / capped



Photo #2

Roth A 30-17 Battery site

Inactive | Shut-down

Formerly served:

Roth A 30-7, A 30-8

Plugged & Abandoned | PA

