



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

Ant Hill Unit 30-42

API: 05-103-09919

Inspection: 700401429



40.10797, -108.20974, 5958.3ft, 293°
05/11/2020 11:33:20 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Pump jack.

Ant Hill Unit 30-42

API: 05-103-09919

Inspection: 700401429



40.10783, -108.2099, 5952.9ft, 278°
05/11/2020 11:31:10 AM



40.10793, -108.20965, 5953.4ft, 272°
05/11/2020 11:32:31 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Separator.

Ant Hill Unit 30-42

API: 05-103-09919

Inspection: 700401429



40.10785, -108.21003, 5958.1ft, 309°
05/11/2020 11:33:52 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 5. Tanks.

Ant Hill Unit 30-42

API: 05-103-09919

Inspection: 700401429



40.10791, -108.21019, 5964.4ft, 45°

05/11/2020 11:34:49 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 6. Tank.

Ant Hill Unit 30-42

API: 05-103-09919

Inspection: 700401429



40.10787, -108.20991, 5950 4ft, 145°
05/11/2020 11:31:33 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

**Photo 7. Storm water channel running on then
off location.**

Ant Hill Unit 30-42

API: 05-103-09919

Inspection: 700401429