

Inspection Photos

5/07/2020

Operator: CAERUS PICEANCE LLC # 10456

Location ID: 335598

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335598



Photo 1: Photo taken from the southeast end of the Location, facing northwest. Photo provides an overview of the Location.



Photo 2: Photo taken from the southeast end of the Location, facing northeast. Photo provides an overview of the Location.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335598



Photo 3: Photo taken from the slopes on the east end of the Location, facing north. Photo shows vegetation establishment over the interim areas.



Photo 4: Photo taken from the northwest end of the Location, facing east. Photo provides an overview of the Location.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335598



Photo 5: Photo taken from the northwest end of the Location, facing south. Photo provides an overview of the Location.



Photo 6: Photo taken from the east end of the Location, facing north. Photo shows areas where Operator appears to have conducted additional work.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC # 10456

Location ID: 335598



Photo 7: Photo taken from east end of the Location, facing east. Photo shows areas of the Location stormwater outlet leading to multiple sediment traps to the southwest of the Location. BMPs appear to have been constructed in accordance with good engineering practices and in proper functioning condition.



Photo 8: Continued from photo 7.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335598



Photo 9: Continued from photo 7..



Photo 10: Continued from photo 7.