

# Inspection Photos

API: 071-07102

Operator: TIMBER CREEK OPERATING

Inspection Date: 5/11/2020



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07102 | Date: 5/11/2020

## Inspection Photos



**Photo 1.** Facing southwest along the main road. The road has been graded and maintained.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07102 | Date: 5/11/2020

## Inspection Photos



**Photo 2.** Facing northeast toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07102 | Date: 5/11/2020

## Inspection Photos



**Photo 3.** Facing toward pumpjack at west side of location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07102 | Date: 5/11/2020

## Inspection Photos



**Photo 4.** Facing east toward the location. Vegetation is well established in the interim reclamation area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07102 | Date: 5/11/2020

## Inspection Photos



**Photo 5.** The well sign is posted at the meter shed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07102 | Date: 5/11/2020