

Inspection Photos

5/07/2020

Operator: CAERUS PICEANCE LLC # 10456

Location ID: 335809

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335809



Photo 1: Photo taken from the north end of the Location, facing southeast. Photo shows Location remains flat, and has not been contoured in accordance with Rule 1004.a. Records indicate this is due to safety concerns regarding the stability of the adjacent landslide area.



Photo 2: Photo taken from the north end of the Location, facing southwest. See comments under photo 1.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335809



Photo 3: Photo taken from south end of the Location, facing north. Photo also shows large areas of the Location where vegetative establishment does not appear to be occurring



Photo 4: Photo taken from the south end of the Location. Photo shows what appears to be an inclinometer installed to monitor seismic and surface movement conditions of the Location.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335809



Photo 5: Photo taken from the north end of the Location, facing north. Photo shows area where access road meets location.



Photo 6: Photo taken from access road, facing south. Photo shows vegetative establishment on the access road.