

Inspection Photos

5/07/2020

Operator: CAERUS PICEANCE LLC # 10456

Location ID: 324425

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 324425



Photo 1: Photo taken from the well coordinates, facing north. Photos 1-4 provide an overview of the Location facing north, east, south and west. Photos show reclamation in process.



Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 324425



Photo 3: See comments under photo 1.



Photo 4: See comments under photo 1.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 324425



Photo 5: Photo taken from the west end of the Location, facing north. Photo shows stormwater diversion ditch and berm.



Photo 6: Photo taken from the west end of the Location, facing north. Photo shows stormwater diversion ditch and berm.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC # 10456

Location ID: 324425



Photo 7: Photo taken from the southwest end of the Location, facing west. Photo shows sediment trap used in conjunction with ditch/berm.



Photo 8: Photo taken from the northwest end of the Location, facing south. Photo shows sediment trap used in conjunction with ditch/berm.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC # 10456

Location ID: 324425



Photo 9: Photo taken from the south end of the Location. Photo shows reclamation in process, as well as wattle BMPs at toe of slope.



Photo 10: Photo taken from the south end of the Location, facing north. Photo shows reclamation in process.