

Inspection Photos

5/07/2020

Operator: CAERUS PICEANCE LLC # 10456

Location ID: 335773

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335773



Photo 1: Photo taken from the west end of the Location, facing northeast. Photo provides an overview of the Location, and interim areas.



Photo 2: Photo taken from the west end of the Location, facing southeast. Photo provides an overview of the Location, and interim areas.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335773



Photo 3: Photo of active wells on Locaiton.



Photo 4: Photo shows sediment trap on the south end of the Location, facing east.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 335773



Photo 5: Continued from photo 4. Photo shows outlet of sediment trap.



Photo 6: Photo taken from the east end of the Location, facing north. Photo shows berm on pad, and interim areas.