

Inspection Photos
Location Name: Lilli Unit 2-1
Location ID: 327035



Photo 1 – Pumping Unit



Photo 2 – Wellhead Sign



Inspection Photos
Location Name: Lilli Unit 2-1
Location ID: 327035



Photo 3 – Crude Oil Tank



Photo 4 – NFPA Label has faded/peeled